# FITNESS360®


FT8058 V-Squat - Plate Loaded



Rubber hammer
Spirit level Allen
wrench More than
2 people Circlip
pliers Adjustable
wrench

## Fastener Overview

Below is an overview of the bolts, washers, and nuts used in this assembly. Please refer to this chart when identifying parts during each assembly step.




#### Step 1:

Connect the standing squat stop connecting frame (#3), the standing squat connecting frame (#4), the pedal reinforcement frame 1 (#5), and the footstep reinforcement frame 2 (#6) to the left frame assembly (#1) and the right frame assembly (#2).

Then, use the method shown to attach the rectangular foot pad (#50) to both the left frame assembly (#1) and the right frame assembly (#2).

- 8x socket head screws M10\*60 (#51)
- 16x flat washers M10-D20 (#57)
- 8x spring washers M10 (#59)
- 8x flat washers M10-D50 (#55)
- 8x hexagon socket head screws M10\*25 (#52)
- 8x hex self-locking nuts M10 (#60)


Tighten all bolts with a wrench before moving to the next step.



#### Step 2:

Use the following method to connect the stop adjustment frame assembly (#9), squat balance weight assembly (#11), gas spring (#13) and standing squat moment arm B assembly (#8)

- 2 x hex socket head screws M10\*20 (#53)
- 2 x Flat Washer M10-D30 (#56)
- 2 x spring washers M10 (#59)
- 6 x hex socket countersunk head screws M10\*20 (#61)




## Step 3:

Connect Step 2, Standing Squat Moment Arm A component (#7) to Step 1 using the following method

- 4x hexagon socket head screws M10\*20 (\*1)
- 4x flat washers M10-D30 (\*3)
- 4x spring washers M10 (\*2)


(\*1) (\*2) (\*3) are pre-assembled parts and are not included in the ingredient list



#### Step 4:


Use the following method to combine the Universal Head Pad (#14), Universal Large Back Pad (#15), 2X Universal Shoulder Pad (#16), and 2X Shoulder Pad Slant Sponge (#17), connect the 3X20 plug (#49) to the standing squat back frame (#10):


- 19x hex socket head screws M8\*25 (#54)
- 19x Flat Washer M8-D16 (#58)



## Step 5:

Use the following method to connect the incline pedal sleeve rod (#12) and Step 4 to the standing squat moment arm B component (#8); use the standing squat moment arm A component (#7) to connect the step 4 connect.






Step 6:

Attach the squat footrest (#18) to step 1 using the method below.

• 4 x hex socket countersunk head screws M8\*16 (#62)



# Fully Installation



## Important Tips

Now that your V-Squat - Plate Loaded unit is fully assembled, take a moment to ensure that it is both level and plumb. Use a spirit level to check the vertical alignment of the guide rods in all directions.

If they are not perfectly vertical, loosen the frame bolts slightly, adjust the alignment, and re-tighten all bolts securely.

## Accessory List

No.	Name and specification	Qty
1	Left shelf	1
2	Right shelf	1
3	V Squat Stop Connecting Frame	1
4	V Squat Connector	1
5	V Squat Foot Strengthener 1	1
6	V Squat Foot Strengthener 2	1
7	V Squat Moment Arm A Component	1
8	V Squat Moment Arm B Component	1
9	Stop adjustment frame assembly	1
10	V Squat Back Plank	1
11	V Squat counterweight components	1
12	Incline pedal sleeve rod	1
13	Gas Spring	1
14	Universal head gasket	1
15	Universal large back pad	1
16	Universal shoulder pad	2
17	Sloping sponge shoulder pad	2
18	Squat pedal	1
49	20 plugs	3
50	Rectangular foot pad	6
51	Hexagon socket head screw M10*60	8
52	Hexagon socket head screw M10*25	8
53	Hexagon socket head screw M10*20	2
54	Hexagon socket head screw M8*25	19
55	Flat washer M10-D50	8
56	Flat washer M10-D30	2
57	Flat washer M10-D20	16
58	Flat washer M8-D16	19
59	Spring washer M10	10
60	Hexagonal self-locking nut M10	8
61	Hexagon socket countersunk head screw M10*20	6
62	Hexagon socket countersunk head screw M8*16	6

# Exploded view

